

**Information Sources and Reporting
for
FY2000 Waste Core Performance Measures**

Core Performance Measure	Source of Information/What Needs to be Reported for Measure
1. Percent of hazardous waste managed at Treatment, Storage and Disposal Facilities (TSDFs) with approved controls in place.	<p>Source: RCRIS What to Report: Status Code OP200 or PC200 - RCRA facilities that have a Final Permit Determination.</p>
2. Percent of underground storage tanks (USTs) meeting requirements.	<p>Source: <i>Semi-Annual Activity Reports (STARS)</i> What to Report: The compliance rate for active USTs that meet the spill/overflow/corrosion protection requirements or temporary closure requirements. The number of permanently closed USTs is collected separately and should not be included in this measure.</p> <p>NOTE: The existing semi-annual report includes a measure for "UST Systems Equipped to Comply with the Requirements for Upgrading". The "Compliance Rate" measure differs in three ways: 1) it is a percentage rate, rather than a number, 2) it includes all temporarily closed USTs, and 3) it should be based on the most current information available. If you believe that the "Equipped to Comply" measure provides a recent and accurate assessment of the actual compliance rate, then you should feel free to use that number (adding in temporarily closed USTs) to calculate the compliance rate. However, if for whatever reason you believe that the "Equipped to Comply" number does NOT provide a recent and accurate assessment of compliance (e.g., if the database is not up to date), please provide your best professional judgment as to the compliance rate in your state. In either case, please inform us whether the information you provide is based on actual data or your best professional judgment.</p>
3. Resource Conservation and Recovery Act (RCRA) Corrective Action (area) sites cleaned up.	<p>Source: RCRIS What to Report: The proposed measure does not yet have a status code, but it will measure area (e.g., acres) as determined by state for high priority sites that need no further action beyond operation/maintenance.</p>

Core Performance Measure	Source of Information/What Needs to be Reported for Measure
4. National Priority List (NPL) sites (area) cleaned up.	Source: CERCLIS What to Report: Acreage for construction completion sites
5. Leaking Underground Storage Tank (LUST)/UST cleanup site status.	Source: Semi-Annual Activity Reports (STARS) What to Report: Confirmed Releases; Cleanups Initiated; Cleanups Completed
6. Toxic releases to groundwater controlled.	Source: RCRIS What to Report: Status Code CA750 - High priority facilities that have been identified by “YE” for yes or “NR” for no release (to be removed).
7. Human exposures to toxins controlled.	Source: RCRIS What to Report: Status Code CA725 - High priority facilities that have been identified by “YE” for yes or “NC” no control necessary (to be removed).